



Morrison Bros. Co.
325 E. 24th St.
P.O. Box 238
Dubuque, IA 52004-0238

Tel: 800-553-2709 ext. 221
Tel: 563-583-0632 ext. 221
Fax: 563-583-5028
E-mail: rzillig@morbros.com
Website: <http://www.morbros.com>

August 16, 2007

Attention: Morrison Distributor

Subject: Fig. 305SA

Morrison Bros. Co. manufactures a 4" top fill swivel adapter listed as Fig. 305SA which is designed to receive and couple to a fill elbow. Once connected, it will allow the full assemblage to swivel without losing integrity in the connection. The adapter is comprised of top and bottom halves that are connected and designed to seal and rotate freely without separating.

It has recently become known to Morrison Bros. Co. that under certain conditions the top and bottom halves of certain swivel adapters may separate if sufficient tensile force is applied which will create a hazardous condition. Adapters in which this condition may exist are confined to units shipped in the last 6-8 months.

To ensure that this condition will not occur, it is required that someone knowledgeable in the operation of these fueling systems and in the operation of swivel adapters inspect all Morrison Fig. 305SA's to make sure the top half of the swivel cannot be separated from the bottom half. If the top half can be separated when the two halves are forced apart, or if any separation movement occurs at all, the swivel must be taken out of inventory and/or removed from service immediately. Do not allow an adapter with this condition to be put in service and/or remain in service. Contact Morrison Bros. Co. and a replacement will be sent at no charge.

It is the duty of Morrison Bros. Co. to warn all MBC distributors of this hazard and to require that proper action be taken and that this notice be forwarded to those who design, install, own, and/or operate fuel storage systems that incorporate this swivel adapter.

Failure to follow the installation instructions and steps for proper and safe operation could result in accidental product spill, property damage, fire, personal injury and/or death.

If you have any questions regarding this notification, please feel free to contact me at (800) 553-2709 ext. 221 or via email at rzillig@morbros.com.

Yours truly,

Rick Zillig
Director QCCS

